
3 1/2 Digit Display, 4-20mA Output


# (Digital Differential Pressure Transmitter)



- 1.
- 2.
- 3.
- 4.
- 5.







# **GENERAL**

PDT Series

, (±),

(±0.25%) (3 1/2

Digit LCD) , (4-20mA)

,

P 가 , Panel key

가

Zero , Range key

## **MODEL** Range

MODEL No	(Range)	(Resolution)
-B15M	±15.0 mmH <sub>2</sub> O	0.1 mmH₂O
-B150M	±150.0 mmH <sub>2</sub> O	0.1 mmH₂O
-B1500M	±1500 mmH <sub>2</sub> O	1 mmH <sub>2</sub> O
-B760H	±760 mmHg	1 mmHg
-D30M	0~30.0 mmH₂O	0.1 mmH₂O
-D300M	0~200.0 mmH <sub>2</sub> O	0.1 mmH₂O
-D3000M	0~2000 mmH <sub>2</sub> O	1 mmH <sub>2</sub> O
-B01K	±1.000 kg/cm <sup>2</sup>	0.001 kg/cm <sup>2</sup>
-B07K	-1.00~7.00 kg/cm <sup>2</sup>	0.01 kg/cm <sup>2</sup>
가		Range

# **SPECIFICATIONS**

**GENERAL** 

Maximum Pressure: Rated Range x 3

Media Compatibility:

Pressure Range: Model Range

**ELECTRICAL** 

Power Supply: Ext DC24V

2 Wire loop power
Connections: 2 screw terminal block
Display: 3 1/2 Digit LCD

Warm up Time: 15 minutes

**TRANSMITTER** 

Connections: 2 Screw terminal block Output Signal: 4-20mADC(limited at

30mADC)

Loop Resistance: 0 - 1100

Zero & Span Adj: One touch Adjustable on

Panel

**PERFORMANCE AT 23** 

Zero Output: 4 mA(Adjustable)
Full Span Output: 20 mA(Adjustable)
Accuracy: ±0.25 % FSO(Include)

±0.25 % FSO(Includes Linearity, Hysteresis &

Repeatability)

Operating Temperature: 0 to 70

**MECHANICAL** 

Pressure Connections: 1/8" PT female Materials: Aluminum Case

Weight 600g

#### STANDARD ACCESSARIES

Tow(2) 1/8" PT plugs for duplicate/ Snap ring Mounting ring, four(4) mounting screws

:


: 2 1/8"

PT Male (NIPPLE) .

1. "HIGH" PORT
2. ( ) "LOW" PORT
PORT

3. "HIGH" PORT .

: PDT Series .



: PORT 가 가

5. OFFSET .(

•

: .

.

PDT series


4 screw terminal

:

가 .


가 (30M )

가 30M 22AWG 가



2 Wire 4 Wire

40mA DC, 18-35VDC 1 (+) 2 (-)



2003.08 ULFA TECHNOLOGY CO.,LTD

#### 기능설명

:

: 가

, ENTER CLEAR .

: RANGE 4~20mA 가

(**OPTION**) : RS232 RS485

**ID** : RS232 RS485 0~255

:

: 가


# 압력계의 설정 및 교정

여기에서는 압력계의 설정을 위한 버튼의 조작방법 및 설정내용에 대하여 설명합니다.


## 조작버튼의 기능

▲ △P	UP	- 설정 값 변경 시 UP버튼 - 옵셋 값 측정모드의 선택/해제 버튼	
<b>PEAK</b>	DOWN	- 설정 값 변경 시 DOWN버튼 - 최대 값 측정모드의 선택/해제 버튼	
	MODE	- 설정모드로 들어가기 - 설정항목 전환	
	ENTER	- 설정 값의 저장 - 최대 값 측정모드시 최대 값 CLEAR - 설정모드에서 나오기	

## 최대값측정모드



#### 옵셋값측정모드



가 : MODE 3
LCD "Int" 가
가 . MODE
"Int"( ) 가
, MODE
" "P4" "P20" "Id" "FAC" "I
nt"MODE .

•

ENTER LCD DISPLAY "SAv "가

, ENTER

: ENTER

, 1

MODE

APO
PEAK O

MODE
"Int"7h

7h

APO
PEAK O

UP,DOWN

APPEAK

APO
PEAK O

LCD
"SAV" 7h
ENTER

ENTER

APO
PEAK O

LCD

SAV" 7h
ENTER

...

# 0.1 ~5.0 0.1 가 . 0.1


( ) 1.0 1 10

DISPLAY

#### 영정조정


영점 조정은 표시부나 전류출력의 영점(ZERO)이 맞지 않을 경우에 이를 보정하는 기능입니다.

:



#### 4mA 전류설정


4mA 4mA7\\
. " 0 " 4mA 7\\
4mA7\\
Range 4mA7\\



### 20mA


20mA 20mA7 ; SPAN(Range) . Range

20mA가



# 통신 ID


통신 ID 는 본기기에 통신 기능이 부가되어 있을 경우 본기 자신의 고유번호(ADDRESS)로 사용하기 위한 것입니다. 따라서 통신기능이 없는 기기는 해당되지 않습니다.



## 공장설정값 불러오기

공장 설정 값은 공장에서 출하 시에 설정된 모든 값들을 의미 합니다.

사용자가 여러 조작을 통하여 설정 값을 변경 시에 잘못 되어 기기가 정상동작을 할 수 없을 때모든 설정상태를 공장 출하시의 상태로 회복하는 기능입니다.



ULFA TECHNOLOGY CO.,LTD TEL 02-806-4403 FAX 02-806-4406